



**AUTO SCAN**  
Vehicle Inspection Services


# Vehicle Inspection Report

Doc ID: AS-301802

Date: 2026-04-26

**Seller Terms:** The inspector or the inspection company shall not be held liable for any incidents or mechanical issues that may arise following the inspection. By signing this agreement, I acknowledge that I waive my right to take any legal action or pursue claims against the inspector or the company regarding the vehicle's condition.

## General Information

Customer Name	dsds
Seller Phone Number	fe5325
Inspection Date	2026-04-26
Document ID	AS-301802
Customer Signature	 _____

## Vehicle Specifications



Vehicle Photo	
---------------	--



<b>Vehicle Brand</b>	Toyota
<b>Interior</b>	Leather
<b>Engine Cylinder</b>	3 Cylinder
<b>Spare Tyres</b>	Available
<b>Number Of Keys</b>	1
<b>VIN Number</b>	234
<b>Mileage</b>	234
<b>Regional Specs</b>	GCC

## Engine & Mechanical Checklist

<b>Battery Type</b>	EFB
<b>Battery Health</b>	3 Out Of 5
<b>Battery Holder</b>	Pass
<b>Battery Holder Photo</b>	



**Engine Upper Cover**

**Pass**


**Engine Upper Photo**



**Engine Lower Cover**

**Pass**

**Engine Lower Photo**



**Hood Holder**

**Pass**

**Hood Holder Photo**





**Fender Liners**

**Pass**

**Fender Liners Photo**





**Turbo / Supercharger**

**Pass**


**Turbo/ Supercharger Photo**



**Engine Idle**

**Pass**

**Engine Idle Photo**



**Engine Oil Filter Cap**

**Pass**

**Engine Oil Filter Photo**




**Radiator**

**Pass**

**Radiator Photo**






**Radiator Hoses & Pipes**

**Pass**


**Radiator Hoses Photo**



**Coolant Level**

**Pass**

**Coolant Photo**



**Engine Oil Level**

**Pass**


**Engine Oil Photo**



**Engine Oil Leaks**

**Pass**

**Oil Leaking Photo**



**Exhaust System**

**Pass**

**Exhaust System Photo**




**Visible Rust**

**Pass**

**Rust Photo**





<b>Transmission Condition</b>	<b>Pass</b>
-------------------------------	-------------



<b>Transmission Fluid Leaks</b>	<b>Pass</b>
---------------------------------	-------------

**Fluid Leak Photo**



## Test Drive & Performance

<b>Drive Shaft</b>	<b>Pass</b>
<b>Noise</b>	<b>Pass</b>
<b>Gear Shifting</b>	<b>Pass</b>

<b>Front Deferential</b>	<b>Pass</b>
<b>Rear Deferential</b>	<b>Pass</b>
<b>Braks Pads Front</b>	<b>Pass</b>
<b>Front Braks Pads Photo</b>	
<b>Braks Discs Front</b>	<b>Pass</b>
<b>Front Braks Discs Photo</b>	
<b>Braks Pads Rear</b>	<b>Pass</b>
<b>Rear Braks Pads Photo</b>	

**Braks Discs Rear**

**Pass**

**Rear Braks Discs Photo**



**ABS Sensor**

**Pass**

**ABS Photo**






**Hand Brake**

**Pass**



**Hand Brake Photo**



**Front Suspension**

**Pass**

**Front Suspension Photo**



	
<b>Rear Suspension</b>	<b>Pass</b>
<b>Rear Suspension Photo</b>	
<b>Wheel Alignment</b>	<b>Pass</b>

## Tyres Condition

Position	Manufacturer	Date	Size	Condition
Front Right Tyre	-	-	-	Good
Front Left Tyre	-	-	-	Good


Rear Left Tyre	-	-	-	Good
Rear Right Tyre	-	-	-	Good
Spare Tyre	-	-	-	Good

## Tyres Details

<b>Front Right Tyre Photo</b>	
<b>Front Left Tyre Photo</b>	
<b>Rear Right Tyre Photo</b>	





Rear Left Tyre Photo



Spare Tyre Photo



## Interior Details

<b>Entertainment System</b>	Not working, need to be replaced
<b>Entertainment System Photo</b>	 A front-facing photograph of a silver Lincoln SUV parked on a paved surface. The car's large, chrome grille with the Lincoln logo is prominent. The license plate is partially visible, showing 'A' and some numbers. The background shows a building and a city skyline under a clear sky.
<b>A/C cooling and controlling</b>	A/C needs service because not cooling properly
<b>A/C System Photo</b>	 A close-up photograph showing a person's hands wearing grey work gloves. The person is working on the engine compartment of a car, with various mechanical parts and hoses visible. The lighting is bright, suggesting an outdoor or well-lit indoor setting.
<b>A/C grilles</b>	Right side damaged or scratches
<b>A/C grilles Photo</b>	

**Windows Operation**

Not working, Need to be replaced


**Windows Photo**







**Seats Adjustment**

Pass

**Seats Adjustment Photo**




	
<b>Door lock / Unlock</b>	Not working properly needs to be repair
<b>Door lock Photo</b>	
<b>Center Console Buttons</b>	Major scratches
<b>Center Console Buttons Photo</b>	



**Cameras**

Scratches


**Cameras Photo**



**Gauges**

Engine check light

**Gauges Photo**





**Rear View Side Mirror**

Left side properly not working


**Rear View Side Mirror Photo**



**Rear View Mirror**

Minor scratches

**Rear View Mirror Photo**



**Steering Wheel Upholstery**

Minor scratches


**Steering Wheel Upholstery Photo**



**Roof Lining**

Hang down/ is gone

**Roof Lining Photo**





**Seats Upholstery**

Major scratches


**Seats Upholstery Photo**



**Seat Belt**

Not working

**Seat Belt Photo**



**Gear Lever**

Damaged


**Gear Lever Photo**




**Trunk Lining**

Minor scratches

**Trunk Lining Photo**





**Armrest & Side Pockets**

Minor scratches


**Armrest & Side Pockets  
Photo**



**Dashboard**

Minor crack

**Dashboard Photo**





**Floor Mats**

Missing



**Floor Mats Photo**



**Wipers**

Front wipers bleed needs to be replaced

**Wipers Photo**



**Front Windscreen**

Minor crack


**Front Windscreen Photo**



**Rear View Mirror**


Minor scratches



**Rear View Mirror Photo**





## Lights Details

<b>Headlights</b>	Damagd needs to be replaced
<b>Headlights Photo</b>	
<b>High Beams</b>	Not working
<b>High Beams Photo</b>	



**Fog Light**

Needs to be replaced


**Fog Light Photo**





**Brake Light**



Crack / damagd



**Brake Light Photo**



	
<b>Reverse Light</b>	Not working properly needs to be replaced
<b>Reverse Light Photo</b>	
<b>Indicators &amp; Hazards</b>	Right side not working
<b>Indicators &amp; Hazards Photo</b>	



	
<b>Indicators &amp; Hazards</b>	Right side not working
<b>Indicators &amp; Hazards Photo</b>	
<b>Number Plate Light</b>	Not working
<b>Number Plate Light Photo</b>	

	
<b>Chassis Condition</b>	Chassis damaged needs to be repair
<b>Chassis Condition Photo</b>	


## Test Drive Performance

<b>Does speedometer work?</b>	<b>Fail</b>
<b>Comments</b>	Fault
<b>Is engine sounds normal?</b>	<b>Fail</b>
<b>Comments</b>	Deaggg



<b>Does transmission gear change smoothly?</b>	<b>Fail</b>
<b>Comments</b>	Swer
<b>Is brakes feel solid and pedal firm?</b>	<b>Fail</b>
<b>Comments</b>	Derw
<b>Does car stop in a straight line?</b>	Sdfer
<b>Comments</b>	Erwed
<b>Does steering pull or vibrate?</b>	<b>Pass</b>
<b>Comments</b>	erfsda
<b>Is suspension smooth (no abnormal noises)?</b>	<b>Pass</b>
<b>Comments</b>	23324
<b>Does emergency brake hold properly?</b>	<b>Pass</b>
<b>Comments</b>	4232
<b>Parking sensors</b>	<b>Pass</b>
<b>Comments</b>	4234

## Exterior Details

<b>Paint conditions Photo</b>	
-------------------------------	--




**Exterior Photo**



**Interior Photo**



**Engine Bay & undercarriage  
Photo**




















<b>Vehicle Diagnostic report</b>	<a href="http://www.wretdfsdfs.com">www.wretdfsdfs.com</a>
<b>Vehicle summary</b>	Overall Very good



## Inspector Details











<b>Inspected By</b>	Abdullah Al Mamun-ID-AS10001
<b>Inspector Designation</b>	Car Inspector

## Vehicle Phtos Gallery



				
Brakes / ABS Operation	Battery Voltage and Charging	Test Drive	Roof and Seals	Suspension
				
Tyres and Wheel	Engine Check	An Electric	Stowage Hatch Locks/	Mismatching



 Brakes / ABS Operation	 Battery Voltage and Charging	 Test Drive	 Roof and Seals	 Suspension
 Tyres and Wheel	 Engine Check	 An Electric	 Stowage Hatch Locks/	 Mismatching

