


Seller Terms: The inspector or the inspection company shall not be held liable for any incidents or mechanical issues that may arise following the inspection. By signing this agreement, I acknowledge that I waive my right to take any legal action or pursue claims against the inspector or the company regarding the vehicle's condition.

General Information

Customer Name	Abdul Matin
Seller Phone Number	01718039823
Inspection Date	2026-04-27
Document ID	AS-742594
Customer Signature	


Vehicle Specifications

Vehicle Photo



Vehicle Brand	Hyundai
Model	Latest
Year	2024
Interior	Leather
Engine Cylinder	6 Cylinder
Spare Tyres	Available
Number Of Keys	2
VIN Number	71616yzvG
Mileage	61414
Regional Specs	Asian

Engine & Mechanical Checklist

Battery Type	Gel Cell
Battery Health	4 Out Of 5
Battery Holder	PASS
Battery Holder Photo	



Engine Upper Cover	PASS
Engine Lower Cover	PASS
Hood Holder	PASS
Fender Liners	Leaking
Turbo / Supercharger	PASS
Engine Idle	PASS
Engine Oil Filter Cap	PASS
Radiator	PASS
Radiator Hoses & Pipes	PASS
Coolant Level	PASS

Engine Oil Level	PASS
Engine Oil Leaks	PASS
Exhaust System	PASS
Visible Rust	PASS
Transmission Condition	PASS
Transmission Fluid Leaks	PASS

Test Drive & Performance

Drive Shaft	Oil leaking, needs to be repair
Noise	PASS
Gear Shifting	PASS
Front Deferential	PASS
Rear Deferential	PASS
Braks Pads Front	PASS
Braks Discs Front	PASS
Braks Pads Rear	PASS
Braks Discs Rear	PASS
ABS Sensor	PASS
Hand Brake	PASS
Front Suspension	PASS
Rear Suspension	Right side XL leaking needs to be replaced
Wheel Alignment	Need to be make alignment

📋 Tyres Condition

Position	Manufacturer	Date	Size	Condition
Front Right Tyre	-	-	-	Fair
Front Left Tyre	-	-	-	Good
Rear Left Tyre	-	-	-	Good
Rear Right Tyre	-	-	-	Good
Spare Tyre	-	-	-	Good

📋 Tyres Details

Front Right Tyre Photo



📋 Interior Details

Entertainment System	Not working, need to be replaced
A/C cooling and controlling	Average
A/C grilles	PASS
Windows Operation	PASS

Seats Adjustment	PASS
Door lock / Unlock	PASS
Center Console Buttons	PASS
Cameras	PASS
Gauges	PASS
Rear View Side Mirror	PASS
Rear View Mirror	PASS
Steering Wheel Upholstery	PASS
Roof Lining	PASS
Seats Upholstery	PASS
Seat Belt	PASS
Gear Lever	PASS
Trunk Lining	PASS
Armrest & Side Pockets	PASS
Dashboard	PASS
Floor Mats	PASS
Wipers	Front wipers bleed needs to be replaced
Front Windscreen	PASS
Rear View Mirror	PASS

Lights Details

Headlights	PASS
------------	------


High Beams	PASS
Fog Light	PASS
Brake Light	PASS
Reverse Light	PASS
Indicators & Hazards	PASS
Indicators & Hazards	PASS
Number Plate Light	PASS
Chassis Condition	PASS

Test Drive Performance

Does speedometer work?	PASS
Is engine sounds normal?	PASS
Does transmission gear change smoothly?	PASS
Is brakes feel solid and pedal firm?	PASS
Does car stop in a straight line?	PASS
Does steering pull or vibrate?	PASS
Is suspension smooth (no abnormal noises)?	PASS
Does emergency brake hold properly?	PASS
Parking sensors	PASS

Exterior Details

Paint conditions Photo



Interior Photo





Vehicle Diagnostic report

<https://drive.google.com/file/d/1N2M1SdPBVqBEed06PD9CpGNHKUY1NRCuP/view?usp=drivesdk>

Vehicle summary

The car is very good condition.

Inspector Details

Inspected By

Jahid Hasan-ID-AS10002

Inspector Designation

Car Inspector

Vehicle Phtos Gallery

